GK-201 GENERATOR REPAIR KIT PARTS LIST

Qty.	Description
	•
1	Armature shaft nut
1	Armature shaft lock washer
1	Armature shaft keyway
1	Armature to bearing spacer
1	Bearing to pulley spacer
1	Bearing wick
1	Wick retainer
1	Bearing
1	Bearing retainer
3	Bearing retainer screws and lock washers
1	Armature terminal kit
1	Field terminal kit
2	Brushes
2	Brush screws and lock washers
2	Brush springs
2	Brush tension arm washers
2	Tension arms
1	Com-end bushing
2	Metal oilers
1	Oil wick
2	Thru bolt lock washers